

## CASE STUDY

## Transportation

# City of Cleburne's Vehicle Maintenance Facility

### OVERVIEW

The city of Cleburne, Texas, operates a vehicle maintenance facility that services the city's buses, trucks and other vehicles.


### PROBLEM

The service bay at the city's vehicle maintenance facility was an open pit, with only a sign warning of its potential danger. When new OSHA guidelines mandated that the service pit was to be covered when not in use, the City of Cleburne was forced to upgrade their facility.

### SOLUTION

Since the service pit is used by repair personnel on a daily basis, the city sought a durable cover light enough for one person to lift, yet strong enough to provide reliable, long-lasting protection. Because weight and ease of use were major concerns, installing heavy steel grating was not a viable option. The city decided on Fibergrate® Corvex® 1-1/2" deep fiberglass molded grating instead because its lightweight panels could easily be handled by a single employee.

In addition to being lightweight and strong, Corvex® grating provides maximum resistance against oil, fuel and other corrosive compounds commonly found in maintenance facilities. When the service pit is not in use, the grating's slip-resistant walking surface also provides city employees with increased safety, reducing the potential for job-related accidents due to poor footing.



### Project Specifications

#### Project

*City of Cleburne's  
Vehicle Maintenance  
Facility  
Cleburne, Texas*

#### Application

Corrosion Resistant  
Walking Surface

#### Products

Fibergrate 1-1/2" Deep  
Corvex® Molded Grating

[www.fibergrate.com](http://www.fibergrate.com)

800-527-4043

**Fibergrate**  
Composite Structures

5151 Beltline Road, Ste. 700 Dallas, TX 75254

Phone: 972-250-1633 • Fax: 972-250-1530

Fibergrate Composite Structures Inc. believes the information contained here to be true and accurate. Fibergrate makes no warranty, expressed or implied based on this literature and assumes no responsibility for the consequential or incidental damages in the use of these products and systems described, including any warranty of merchantability or fitness. Information contained here can be for evaluation only.

©Fibergrate Inc. 2005 Part No. 881110

Printed in the USA